

Uponor ProPEX® lead-free (LF) brass saddle adapters

Project information	
Job name:	Location:
Engineer:	Date submitted:
Contractor:	Submitted by:
Manufacturer's representative:	Approved by:

Technical data


Material PP-RCT

Temp/pressure ratings 73 °F (23 °C) at 340 psi (23.44 bar) 140 °F (60 °C) at 190 psi (13.1 bar)

180 °F (82 °C) at 100 psi (6.9 bar)

Product information and application use

Use Uponor ProPEX lead-free (LF) brass adapters with Uponor PP-RCT mechanical pipe to convey water for hydronic heating and cooling or industrial applications.



(FOR SADDLE/OUTLET FUSION)

Part name	Part no.	End Type 1	End Type 2	Prop 65 label required?
Uponor ProPEX LF Brass Saddle Adapter, 1 1/2" / 3/4" PP-RCT x 1/2" PEX, for Outlet Fusion	PR4511550	Saddle 1-1/2"	ProPEX 1/2"	No
Uponor ProPEX LF Brass Saddle Adapter, 2" / 3/4" PP-RCT x 3/4" PEX, for Outlet Fusion	PR4512075	Saddle 2"	ProPEX 3/4"	Yes

Part name	Part no.	Codes	Standards	Listings
Uponor ProPEX® lead-free (LF) brass	All	CMCIIMCIUMC	ASTM F1960 ASTM E84 NSF-	ICC-ES-PMG 1106 IAPMO-R&T
saddle adapters	All	CIVICIINICIONIC	14 ASTM F2389 CSA B137.11	8358 QAI P321-5 IAPMO K-12775

Installation	Related applications

For the PEX side, use the appropriate ProPEX ring and fitting. For the PP-RCT side, use approved fusion connection methods. For additional information, refer to the Uponor PP-RCT manual.

Hydronic heating and cooling systems

Industrial

Footnotes	Contact i	Contact information		
	Uponor Inc.	Uponor Ltd.		
	5925 148th Street West	6510 Kennedy Road		
	Apple Valley, MN 55124	Mississauga, ON L5T 2X4		
	T 800.321.4739	T 888.594.7726		
	F 952.891.2008	F 800.638.9517		