

PP-RCT accessories

Project Information

| | |
|--------------------------------|-----------------|
| Job name: | Location: |
| Engineer: | Date submitted: |
| Contractor: | Submitted by: |
| Manufacturer's representative: | Approved by: |



| Part name | Part no. | A [inch] | B [inch] | C [inch] |
|-----------------------------|-----------|----------|----------|----------|
| Uponor PP-RCT Marking Guide | PR6041000 | 1.969 | 1.575 | 0.276 |
| Uponor PP-RCT Repair Plug | PR6071000 | 3.11 | 0.433 | 0.433 |

| Part name | Part no. | Codes | Standards | Listings |
|---|-----------|-------|-----------|--------------------------|
| PP-RCT accessories | All | - | - | - |
| In addition, the following parts have additional codes, standards, or listings: | | | | |
| Uponor PP-RCT Repair Plug | PR6071000 | | ASTM E84 | QAI P321-5 IAPMO K-12775 |

| Installation | Related applications |
|--------------|-------------------------------|
| - | AquaSAFE™ Fire Safety Systems |

| Footnotes | Contact information | | |
|---|--|---|---|
| - | <table border="0"> <tr> <td> Uponor Inc. 5925 148th Street West Apple Valley, MN 55124 T 800.321.4739 F 952.891.2008 </td> <td> Uponor Ltd. 6510 Kennedy Road Mississauga, ON L5T 2X4 T 888.594.7726 F 800.638.9517 </td> </tr> </table> | Uponor Inc. 5925 148th Street West Apple Valley, MN 55124 T 800.321.4739 F 952.891.2008 | Uponor Ltd. 6510 Kennedy Road Mississauga, ON L5T 2X4 T 888.594.7726 F 800.638.9517 |
| Uponor Inc. 5925 148th Street West Apple Valley, MN 55124 T 800.321.4739 F 952.891.2008 | Uponor Ltd. 6510 Kennedy Road Mississauga, ON L5T 2X4 T 888.594.7726 F 800.638.9517 | | |